

MEMO

TO: File

FROM: W. R. Smith

SUBJECT: Nick Kritsos First National Bank Wells, located in the
NW $\frac{1}{4}$, Sec. 17, T-1N-R-43W

1-878-4833

On July 6, 1966, I visited subject wells to determine the nature of water produced, and possibly locate drainage of said water while drilling.

This investigation was predicated on Mr. Kritsos' comment that the well was shut-in while stock was in the field because of the salty nature of the water.

I found the well that he is working on, in the SW $\frac{1}{4}$ NW $\frac{1}{4}$, with a valve on the top. The volve was leaking a small amount of water with a very saline taste. The volume was insufficient to flow into the reserve pit, and soaked into the ground.

The other, an inactive well, located in the NE $\frac{1}{4}$ NW $\frac{1}{4}$, was capped, but no leak and no pollution problem was apparent.



00038367