

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403995391

Date Received:
11/14/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

ENERGY, QB

ecmc.inspections@qb-energy.com

Kellerby, Shaun

shaun.kellerby@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 713400446

Inspection Date: 10/31/2024

FIR Submit Date: 11/05/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334316

Location Name: KEINATH FEDERAL-68S96W Number: 18SWNE County: _____

Qtrqtr: SWNE Sec: 18 Twp: 8S Range: 96W Meridian: 6

Latitude: 39.352770 Longitude: -108.148746

FACILITY - API Number: 05-077-

-00

Facility ID: 334316

Facility Name: KEINATH FEDERAL-68S96W Number: 18SWNE

Qtrqtr: SWNE Sec: 18 Twp: 8S Range: 96W Meridian: 6

Latitude: 39.352770 Longitude: -108.148746

CORRECTIVE ACTIONS:

2 CA# 200290

Corrective Action: Comply with CECMC Storm water rules

Date: 11/20/2024

Response: CA COMPLETED

Date of Completion: 11/08/2024

Operator
Comment: Filled holes caused by erosion

ECMC Decision: _____

ECMC Representative:	
-------------------------	--

OPERATOR COMMENT AND SUBMITTAL

Comment:

--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Terry Martinez Signed: _____

Title: Compliance Date: 11/14/2024 2:29:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403995404	Filled holes caused by erosion

Total Attach: 1 Files