

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2024

Submitted Date:

11/15/2024

Document Number:

694500735**FIELD INSPECTION FORM**Loc ID 311768 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 7125Name of Operator: BEEMAN OIL & GAS INCAddress: 13635 E 104TH AVENUE STE 400City: COMMERCE CITY State: CO Zip: 80022**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Lawton, Lisa	970-846-4639	lisa@beemanoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223110	WELL	PR	06/25/1997	OW	081-06472	ELK SPRINGS UNIT 3	EI
311768	LOCATION	AC			-	ELK SPRINGS UNIT- 65N98W 30NWSE	EI
484741	SPILL OR RELEASE	CL	08/17/2023		-	SPILL/RELEASE POINT	EI

General Comment:

ECMC staff Kris Neidel inspected the Elk Springs #4 wellpad and the release point for REM # 31024. Weather was 50 degrees. The following was observed; oil trash and filter socks and ground inside of the pumphouse adjacent to the well. The spill/release point for Remediation #31024, below the #4 wellpad is observable as black stained soil. Corrective Actions: Remediation Project 31024 is delinquent by all metrics; reporting and remediation. By rule, quarterly reporting is required. A Form 27 with a robust plan to delineate any impact shall be submitted (Along the entire spill path). Root cause analysis shall be included. The piping that failed/allowed water to be discharged to this point shall be removed and investigated. See Photos attached.

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Inadequate		
Comment:	The spill/release point for Remediation #31024, below the #4 wellpad is observable as black stained soil. It appears that nothing has been done at the release point.			
Corrective Action:	A Form 27 with a robust plan to delineate any impact shall be submitted (Along the entire spill path). Root cause analysis shall be included. The piping that failed/allowed water to be discharged to this point shall be removed and investigated.			Date: 11/22/2024

Spill/Remediation:

Comment:	spill #484741 was observed on 7/6/2023 and it appears that nothing has been done to clean up spill. No communication has been made with the ECMC on this spill, since the initial Form 27 was filed.			
Corrective Action:	A Form 27 with a robust plan to delineate any impact shall be submitted (Along the entire spill path). Root cause analysis shall be included. The piping that failed/allowed water to be discharged to this point shall be removed and investigated.			Date: 11/22/2024

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500736	photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6788780