

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



Photo # 9975 From entrance to location



Photo # 9976 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



Photo # 9977 Location



Photo # 9978 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



Photo # 9979 Location



Photo # 9980 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



Photo # 9981 Location



Photo # 9982 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



Nov 14, 2024 at 12:13:58 PM



Nov 14, 2024 at 12:08:14 PM
CO

Photo # 9983 Location

Photo # 9984 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868

Nov 14, 2024 at 12:02:23 PM



Photo # 9985 Location

Nov 14, 2024 at 12:12:49 PM



Photo # 9986 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



Photo # 9987 Stored stockpile on location (additionally stockpiled materials lack Stormwater BMP's & stockpile is interfering with interim reclamation)

Photo # 9988 Stored stockpile on location (additionally stockpiled materials lack Stormwater BMP's & stockpile is interfering with interim reclamation)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



Photo # 9989 Stored stockpile on location (additionally stockpiled materials lack Stormwater BMP's & stockpile is interfering with interim reclamation)



Photo # 9990 Stored stockpile on location (additionally stockpiled materials lack Stormwater BMP's & stockpile is interfering with interim reclamation)