

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404001722

Date Received:

11/20/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708303020

Inspection Date: 11/04/2024

FIR Submit Date: 11/05/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

#### LOCATION - Location ID: 335219

Location Name: ACCO TOSCO-66S95W Number: 34SWNE County: \_\_\_\_\_

Qtrqtr: SWNE Sec: 34 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.482929 Longitude: -107.982363

#### FACILITY - API Number: 05-045- -00 Facility ID: 335219

Facility Name: ACCO TOSCO-66S95W Number: 34SWNE

Qtrqtr: SWNE Sec: 34 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.482929 Longitude: -107.982363

### CORRECTIVE ACTIONS:

2 CA# 200258

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 11/20/2024

Response: CA COMPLETED

Date of Completion: 11/18/2024

Operator Comment: Access road and pad have been bladed. Ditches have been pulled / cleaned out to control sediment. BMPs have been maintained. Corrective action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Access road and pad have been bladed. Ditches have been pulled / cleaned out to control sediment. BMPs have been cleaned out and maintained. Corrective Action #200258 has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 11/20/2024 4:53:44 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

404001722	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files