

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2024

Submitted Date:

11/25/2024

Document Number:

699700443**FIELD INSPECTION FORM**Loc ID 322428 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**ECMC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 600 TRAVIS STREET SUITE 5050City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Roberts, James		j75rober@blm.gov	BLM meeker
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	
Schultz, Scott		Scott.Schultz@coag.gov	CO AG
Burn, Diana		diana.burn@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Frost, Joe	7137423642	jfrost@americanhelium.us	American Helium President
Schroeder, Siera	7197231542	siera.schroeder@state.co.us	Enforcement Advisor

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210479	WELL	SI	06/01/2020	GW	045-06235	FEDERAL 2-11	EI

**General Comment:**

ECMC Environmental Inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Other

#

Comment: Active gas leak originating at the wellhead. See email notification Doc #2573189 for more information.

Corrective Action: Locin shall securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER		<50 BBLS	PLASTIC AST		,	
Comment:						
Corrective Action:						Date: <input type="text"/>

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Inadequate secondary containment for the 12 bbl Produced Water plastic AST.			
Corrective Action:	Install liner material to ensure spill or released materials will be maintained with containment structure. (PW)			
				Date: <input type="text"/>

**Venting:**

Yes/No				
Comment:				
Corrective Action:				
				Date: <input type="text"/>

**Flaring:**

Type				
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

