

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2024

Submitted Date:

11/19/2024

Document Number:

714300158

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Brown, Kari 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
,		cogcc@kpk.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	
Peterson, John		jpeter@kpk.com	KPK environmental

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487114	SPILL OR RELEASE	AC			-	James A Damiana	EI

General Comment:

This is an environmental inspection to determine progress on Spill ID 487114/Remediation Project No 37597. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds present throughout the location			
Corrective Action:	Comply with Rule 606.			Date: 11/26/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type				
Comment:	Cattle fencing surrounds open excavation, however, wildlife footprints were noted in the bottom of the excavation. Fencing is not adequate to protect wildlife.			
Corrective Action:	Secure access to excavation in compliance with Rule 913.b.(5).B.i and in a manor that is protective to wildlife.			Date: 12/03/2024
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	487114	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remedial excavation is open. The floor of the excavation was saturated, likely from recent snow events. Flowlines and concrete produced water vault remain present in the open excavation. Holes were noted in the concrete produced water vault (likely occurred during excavation).

Corrective Action: Operator will comply with the implementation schedule and Conditions of Approval for all remaining remediation of soil impacts, reclamation and reporting established in the ECMC Remediation Project No. 37597. Operator shall provide an updated Form 27 for Remediation #37597.

Date: 11/17/2024

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Inadequate		
Comment	Soil stockpile marked 'contaminated' stored on location. Stockpile liner is beginning to tear and soil has overflowed berms in some locations. E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.			
Corrective Action	Prior to spill/remediation closure Operator will collect soil samples from underneath the observed soil stockpile area and surrounding areas where the stockpile has overflowed berms.			Date: _____

Spill/Remediation:

Comment: Spill ID 487114 remains open.

Corrective Action: Operator will submit a Form Supplemental which requests closure of the Spill referencing Remediation #37597.

Date: 09/30/2024

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403999481	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6792259
714300159	Insp Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6792231