

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/25/2024

Submitted Date:

11/26/2024

Document Number:

713601666

FIELD INSPECTION FORM

Loc ID 334549 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 66561
Name of Operator: OXY USA INC
Address: PO BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
OXY		ECMCInspections@Oxy.com	
Newville, Toni		toni_newville@oxy.com	
Sanchez, Chris		chris.sanchez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
334549	LOCATION	AC			-	Sheep Mountain Unit Drill Site 2	RI

General Comment:

This is a reclamation inspection at the Sheep Mountain Unit/Drill Site 2.
See attached photos and additional details within this report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
	Piles	Inadequate		
Comment	There are multiple waste piles stored on location from the abandoned well and pit remediation. The piles are not properly stored and appear to have been spread outside of containment. The material has fallen outside of berm and the liner and berm are compromised.			
Corrective Action	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905. Contact ECMC EPS staff.			Date: 12/02/2024

Spill/Remediation:

Comment:	Remediation of the abandoned well and pit remains in process. There still appears to be impacted material along the excavated side of the pit area.			
Corrective Action:				Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [The cattleguard along the access road has filled in with sediment and will need to be cleaned out.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	115234	403200810	
	115234	403200810	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601667	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6802092