

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404009034

Date Received:
11/27/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Luke Kelly</u>	<u>970-939-6353</u>	<u>lkelly@civiresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713901127
Inspection Date: 10/23/2024 FIR Submit Date: 10/25/2024 FIR Status: _____

Inspected Operator Information:

Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Company Number: 10633
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 331898

Location Name: NEWMAN-62N64W Number: 32CNW County: _____
Qtrqtr: CNW Sec: 32 Twp: 2N Range: 64W Meridian: 6
Latitude: 40.098729 Longitude: -104.579643

FACILITY - API Number: 05-123-00 Facility ID: 331898

Facility Name: NEWMAN-62N64W Number: 32CNW
Qtrqtr: CNW Sec: 32 Twp: 2N Range: 64W Meridian: 6
Latitude: 40.098729 Longitude: -104.579643

CORRECTIVE ACTIONS:

1 CA# 200088

Corrective Action: Comply with Rule 1105.f.(2). Form 44 should have been submitted within 90-days of completing abandonment. Date: 11/25/2024

Response: CA COMPLETED Date of Completion: 11/25/2024

Operator Comment: Operator reported that records show the flowline was abandoned in place on 11/7/2014. The F42 was then submitted well after the fact to close out the Well's FM6SR. The Operator was also able to confirm that the entirety of the ~4000-ft line was abandoned in place on 11/7/2014, so the FM42 is related to the entire wellhead flowline.

ECMC Decision: _____

ECMC
Representative:

2 CA# 200089

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: _____

Response: CA COMPLETED

Date of Completion: 11/26/2024

Operator Comment: The operator has provided photo evidence showing that the area has been mowed to manage weeds and inter-seeded to comply with Rule 1004.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 11/27/2024 9:57:57 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404009034	FIR RESOLUTION SUBMITTED
404009094	Inspection Report Resolution

Total Attach: 2 Files