

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404012291

Date Received:
12/02/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|-----------------------|-------------------|--|
| <u>Lacey Granillo</u> | <u>5057870118</u> | <u>lgranillo@logosresourcesllc.com</u> |

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001528
Inspection Date: 11/20/2024 FIR Submit Date: 11/25/2024 FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC Company Number: 10679
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 325009

Location Name: OLGUIN-N32N6W Number: 18SWNE County: _____
Qtrqtr: SWNE Sec: 18 Twp: 32N Range: 6W Meridian: N
Latitude: 37.019732 Longitude: -107.538598

FACILITY - API Number: 05-067-00 Facility ID: 325009

Facility Name: OLGUIN-N32N6W Number: 18SWNE
Qtrqtr: SWNE Sec: 18 Twp: 32N Range: 6W Meridian: N
Latitude: 37.019732 Longitude: -107.538598

CORRECTIVE ACTIONS:

1 CA# 200687

Corrective Action: Comply with rule 606, remove and properly dispose of debris. Date: 12/02/2024

Response: CA COMPLETED Date of Completion: 12/02/2024

Operator Comment: Removed all weeds and debris from location.

ECMC Decision: _____

ECMC
Representative:

2 CA# 200688

Corrective Action: Comply with rule 606, remove unused equipment from location.

Date: _____

Response: CA COMPLETED

Date of Completion: 12/02/2024

Operator Comment: Previous email sent to Corey Mcdonough on 3/19/24- LOGOS Operating is currently attempting to connect the pipeline to IKAV for this location. Curtis Pattillo was the inspector, but I believe is no longer with the ECMS, so I wanted to notify you.

ECMC Decision: _____

ECMC
Representative:

3 CA# 200689

Corrective Action: Comply with rule 1002f. Install or repair required BMPs.

Date: 12/02/2024

Response: CA COMPLETED

Date of Completion: 12/02/2024

Operator Comment: Repaired BMPs and rutts on location.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All weeds, debris and rutts have been taken care of.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lacey Granillo

Signed: _____

Title: Regulatory Specialist

Date: 12/2/2024 3:31:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| Document Number | Description |
|-----------------|-----------------------------|
| 404012291 | FIR RESOLUTION SUBMITTED |
| 404012316 | Olguin 1 714001528 location |
| 404012318 | Olguin 1 714001528 location |
| 404012319 | Olguin 1 714001528 location |

Total Attach: 4 Files