


Inspection Photos
Location Name: Weaver 24-03 1S46W
API Number: 125-10905



1. Well sign on meter shed at well location.



2. Wellhead cemented to surface and SI for 5 day wait for cut and cap work.

Inspection Photos
Location Name: Weaver 24-03 1S46W
API Number: 125-10905



3. Meter shed on well location.



4. Gas meter inside meter shed. Air gapped for P&A.

Inspection Photos
Location Name: Weaver 24-03 1S46W
API Number: 125-10905



5. Meter shed at Weaver 1-3, 125-07327 where flowline excavation is being done for flowline abandonment.



6. Flowlines at Weaver 1-3 excavated and purged for abandonment.