

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/25/2024

Submitted Date:

11/27/2024

Document Number:

713601674**FIELD INSPECTION FORM**Loc ID 333349 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
OXY		ECMCInspections@oxy.com	
Newville, Toni		toni_newville@oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
333349	LOCATION	AC			-	SHEEP MOUNTAIN UNIT- 628S70W 2NENE	RI

General Comment:

This is a reclamation inspection at the Sheep Mountain Drill Site #5.
See attached photos and additional details within this report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	The orange safety fences around the excavated areas have fallen down and requires maintenance.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental				
Waste Management:				
Type	Management	Condition	GPS (Lat) (Long)	
	Piles	Inadequate		
Comment	There is a pile of waste material stored on a liner but the berms are insufficient and material has fallen outside of containment.			
Corrective Action	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.			Date: 12/06/2024
Spill/Remediation:				
Comment:	Pit closure remediation is in process.			
Corrective Action:				Date: _____
Emission Control Burner (ECB): _____				
Comment:				
Pilot: _____	Wildlife Protection Devices (fired vessels): _____			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues were observed during this inspection.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404009211	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6803447
713601675	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6803435