

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404014711

Date Received:

12/04/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

7 of 12 CAs from the FIR responded to on this Form

7 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Arauz, Steven

steven.arauza@state.co.us

Laramie

cogccnotifications@laramie-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718100019

Inspection Date: 11/12/2024

FIR Submit Date: 12/02/2024

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 487592

Location Name: Laramie Number: 0993-29-01 County: _____

Qtrqtr: NENE Sec: 29 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.254781 Longitude: -107.784158

FACILITY - API Number: 05-077- -00 Facility ID: 487592

Facility Name: Laramie Number: 0993-29-01

Qtrqtr: NENE Sec: 29 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.254781 Longitude: -107.784158

CORRECTIVE ACTIONS:

1 CA# 200762

Corrective Action: Comply with Rule 605.a

Date: 11/19/2024

Response: CA COMPLETED

Date of Completion: 11/18/2024

Operator Comment: Sign has been repaired and properly placed.

ECMC Decision: _____

ECMC
Representative:

3 CA# 200764

Corrective Action: Install or repair BMPs pursaunt to Rule 1002.f, the Form 2A permitted SWMP and Layout Drawing

Date: 11/19/2024

Response: CA COMPLETED

Date of Completion: 11/23/2024

Operator
Comment:

Sediment trap has been installed,

ECMC Decision:

ECMC
Representative:

4 CA# 200765

Corrective Action: Install or repair BMPs pursaunt to Rule 1002.f, the Form 2A permitted SWMP and Layout Drawing

Date: 11/19/2024

Response: CA COMPLETED

Date of Completion: 11/23/2024

Operator
Comment:

Stormwater diversion trench has been installed

ECMC Decision:

ECMC
Representative:

5 CA# 200766

Corrective Action: Install or repair BMPs at the cut/fill slopes pursuant to Rule 1002.f

Date: 11/19/2024

Response: CA COMPLETED

Date of Completion: 11/23/2024

Operator
Comment:

BMPs have been repaired.

ECMC Decision:

ECMC
Representative:

6 CA# 200767

Corrective Action: Install or repair BMPs pursaunt to Rule 1002.f, the Form 2A permitted SWMP and Layout Drawing

Date: 11/19/2024

Response: CA COMPLETED

Date of Completion: 11/28/2024

Operator
Comment:

V-ditch instlaed

ECMC Decision:

ECMC
Representative:

8 CA# 200769

Corrective Action:

Date: 11/19/2024

Install or repair BMPs pursuant to Rule 1002.f, the Form 2A permitted SWMP and Layout Drawing

Response: CA COMPLETED

Date of Completion: 11/23/2024

Operator Comment: diversion ditch has been connected

ECMC Decision:

ECMC Representative:

11 CA# 200772

Corrective Action: Install or repair BMPs pursuant to Rule 1002.f, the Form 2A permitted SWMP and Layout Drawing

Date: 11/19/2024

Response: CA COMPLETED

Date of Completion: 11/23/2024

Operator Comment: road has been stabilized.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The remainder will be completed once the snow melts and we are able to access the ground.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed:

Title: Regulatory Analyst

Date: 12/4/2024 9:00:43 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404014711	FIR RESOLUTION SUBMITTED
404014721	CA Photos

Total Attach: 2 Files