

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404012377

Date Received:

12/06/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Fritzler, Gene

gfritzler12@gmail.com

Heibel, Krystal

krystal.heibel@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 701603748

Inspection Date: 07/25/2023

FIR Submit Date: 08/07/2023

FIR Status: _____

Inspected Operator Information:

Company Name: FRITZLER RESOURCES INC

Company Number: 31257

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 312314

Location Name: FEHRINGER-612N52W Number: 28SWNE County: LOGAN

Qtrqr: SWNE Sec: 28 Twp: 12N Range: 52W Meridian: 6

Latitude: 40.988963 Longitude: -103.179494

FACILITY - API Number: 05-075-00 Facility ID: 221192

Facility Name: FEHRINGER Number: 1

Qtrqr: SWNE Sec: 28 Twp: 12N Range: 52W Meridian: 6

Latitude: 40.988963 Longitude: -103.179494

CORRECTIVE ACTIONS:

1 CA# 177542

Corrective Action: PROPERLY REMOVE/REMEDiate AFFECTED SOIL IN PJ SHED AND BELOW GEAR BOX. COMPLY WITH RULE 906

Date: 08/08/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Operator Comment: All E&P waste near pumping unit was removed and stockpiled for disposal.

ECMC Decision: _____

ECMC
Representative:

2 CA# 177543

Corrective Action: COMPLY WITH RULE 606

Date: 08/14/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Operator Comment: All Equipment such as tubing has been removed, Some small containers have been left to provide lube oil for the engine

ECMC Decision:

ECMC
Representative:

3 CA# 177544

Corrective Action: INSTALL SIGNAGE TO COMPLY WITH RULE 605.g.

Date: 10/07/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Operator Comment: The sign has been improved with addition of Operators Name and Emergency Contact information, New signs have not arrived but will be installed as soon as available

ECMC Decision:

ECMC
Representative:

4 CA# 177545

Corrective Action: INSTALL SIGNAGE TO COMPLY WITH RULE605.d.

Date: 10/07/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Operator Comment: Well sign was brought into compliance with 605 d. (1), A,B,C with addition of the operators name and Emergency contact no.
A new sign will be installed in 3 weeks.

ECMC Decision:

ECMC
Representative:

5 CA# 177546

Corrective Action: COMPLY WITH RULE 606

Date: 08/14/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Operator Comment: All weed , road maintenance, as well as all unused equipment and trash have been removed.

ECMC Decision:

ECMC
Representative:

6 CA# 177547

Corrective Action: COMPLY WITH RULE 606 AND 906

Date: 09/07/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Trash, extra equipment and waste has been removed.

We have increased our general maintenance and upkeep on the leases.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed:

Date: 12/6/2024 1:27:37 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404012413	Pumping Unit Base
404012414	Lease Road
404012445	East Side of Unit Base
404017595	Engine House

Total Attach: 4 Files