

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404012377

Date Received:

12/06/2024

## FIR RESOLUTION FORM

**Overall Status:**

**CA Summary:**

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name

Phone

Email

Fritzler, Gene

gfritzler12@gmail.com

Heibel, Krystal

krystal.heibel@state.co.us

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 701603748

Inspection Date: 07/25/2023

FIR Submit Date: 08/07/2023

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: FRITZLER RESOURCES INC

Company Number: 31257

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

**LOCATION - Location ID: 312314**

Location Name: FEHRINGER-612N52W Number: 28SWNE County: LOGAN

Qtrqtr: SWNE Sec: 28 Twp: 12N Range: 52W Meridian: 6

Latitude: 40.988963 Longitude: -103.179494

**FACILITY - API Number: 05-075- -00 Facility ID: 221192**

Facility Name: FEHRINGER Number: 1

Qtrqtr: SWNE Sec: 28 Twp: 12N Range: 52W Meridian: 6

Latitude: 40.988963 Longitude: -103.179494

**CORRECTIVE ACTIONS:**

1 CA# 177542

Corrective Action: PROPERLY REMOVE/REMEDiate AFFECTED SOIL IN PJ SHED AND BELOW GEAR BOX. COMPLY WITH RULE 906

Date: 08/08/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Operator Comment: All E&P waste near pumping unit was removed and stockpiled for disposal.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 177543

Corrective Action: COMPLY WITH RULE 606

Date: 08/14/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Operator Comment: All Equipment such as tubing has been removed, Some small containers have been left to provide lube oil for the engine

ECMC Decision:

ECMC  
Representative:

3 CA# 177544

Corrective Action: INSTALL SIGNAGE TO COMPLY WITH RULE 605.g.

Date: 10/07/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Operator Comment: The sign has been improved with addition of Operators Name and Emergency Contact information, New signs have not arrived but will be installed as soon as available

ECMC Decision:

ECMC  
Representative:

4 CA# 177545

Corrective Action: INSTALL SIGNAGE TO COMPLY WITH RULE605.d.

Date: 10/07/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Operator Comment: Well sign was brought into compliance with 605 d. (1), A,B,C with addition of the operators name and Emergency contact no.  
A new sign will be installed in 3 weeks.

ECMC Decision:

ECMC  
Representative:

5 CA# 177546

Corrective Action: COMPLY WITH RULE 606

Date: 08/14/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Operator Comment: All weed , road maintenance, as well as all unused equipment and trash have been removed.

ECMC Decision:

ECMC  
Representative:

6 CA# 177547

Corrective Action: COMPLY WITH RULE 606 AND 906

Date: 09/07/2023

Response: CA COMPLETED

Date of Completion: 10/12/2023

Trash, extra equipment and waste has been removed.

We have increased our general maintenance and upkeep on the leases.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Date: 12/6/2024 1:27:37 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
404012377	FIR RESOLUTION SUBMITTED
404012413	Pumping Unit Base
404012414	Lease Road
404012445	East Side of Unit Base
404017595	Engine House

Total Attach: 5 Files