

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Unocal/GM 44-1

Location ID: 324080

Date: 12/5/2024



Photo # 0358 Entrance to location



Photo # 0379 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Unocal/GM 44-1

Location ID: 324080

Date: 12/5/2024



Photo # 0359 Location



Photo # 0365 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Unocal/GM 44-1

Location ID: 324080

Date: 12/5/2024



Photo # 0377 Location



Photo # 0394 NE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Unocal/GM 44-1

Location ID: 324080

Date: 12/5/2024



Photo # 0395 NW corner of location



Photo # 0372 PRV vent lines do not comply with CECMC pressure safety device rules

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Unocal/GM 44-1

Location ID: 324080

Date: 12/5/2024



Photo # 0374 PRV vent lines do not comply with CECMC pressure safety device rules




Photo # 0389 Debris

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Unocal/GM 44-1

Location ID: 324080

Date: 12/5/2024



Photo # 0393 Debris



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources