

1876 RESOURCES HAILEY 342

11/15/2024

P (1) of (1)

ON: 10:50 OFF: 13:25

OPERATOR: 1876 RESOURCES FORMER CUB CREEK

LOCATION: HAILEY 342 318870 + DRAINAGE

SPILL ID: 485972

PPE: LEVEL D + FR

WEATHER: PARTLY CLOUDY 44°F SLIGHT BREEZE

ECMC: LAUREL ANDERSON

OP. PERSONNEL: 1876 CHRISTIAN COMBS & BRIAN WALTERS

OP. CONTRACTOR: CDH ELLIE NAKA RETURN @ 11:39

ISSUES OBSERVED:

GENERAL GOOD HOUSEKEEPING

- LEAKY EQUIPMENT, MANWAY BOLTS RUSTED (BASE)
- STAINED SOIL / SECONDARY CONTAINMENT
- SHEEN ON WATER IN 1ST SECONDARY CONTAINMENT
- VISIBLE PRODUCT
- UNUSED EQUIPMENT (VALVES, ENRADO, PARTS, SHIELDING)
- TRASH - MINOR
- WEEDS - ALONG FENCING (MINOR)

STORMWATER

- BMPs AROUND LOCATION REQUIRE MAINTENANCE
- SEDIMENT TRAPERS TO HAVE DISCHARGED OFF - LOCATION ON SOUTHERN PORTION OF PAD

SIGNAGE

- MAJORITY OF SIGNAGE HAS BEEN UPDATED TO REFLECT CURRENT OPERATOR
- SOME SIGNAGE IS FADED / PEELING & NEEDS REPLACED

SPILLS

- SIGNIFICANT STAINING AROUND / WITH SOOL (CONDENSATE TANK + CORRUGATED STEEL DRAIN)

1876 RESOURCES HALEY 3H2

11/15/2024

page 2 of 4

- STAINING AT COMPRESSOR SKID
- STAINING + FREE PRODUCT w/in AST DIKE + CONTAINMENT LINER / PEA GRAVEL / PRECIPITATION

Send Insp TO C.C.

Insp. SEND ALL Insp TO FOR 1876 RESOURCES
CHRISTIAN.COMBS@1876RESOURCES

NO RYAN, TRENTON,
LEFT ↑ COO

1876 RESOURCES HALEY 342

11/15/2024

p(2) of (3)

SPILL ID 485972

SEPARATOR

STAINED SOIL VISIBLE BENEATH SEP. SKID

DISCUSSED NEED FOR SCREENING +
SAMPLING ALONG SIDEWALLS

DISCUSSED PAD SAMPLES OUTSIDE OF
CONTAINMENT IF CLEAR (NO DETECTABLE
ORGANICS) COULD BE USED AS BG. TO
CLEAR METALS + SS.

PLAN TO HAND DIG @ SS02 @ 5' TO DEFINE THE
EXTENT + GET LOWER PID.

NEED TO OVER EXCAVATE SS02 @ 2'

