

TEP Rocky Mountain LLC
Federal RGU 31-30-198
Location ID: 316487



Stained soil at and around condensate tank



Vent riser caps missing

**TEP Rocky Mountain LLC
Federal RGU 31-30-198
Location ID: 316487**



Location from Northeast corner



Production equipment from Northeast corner

**TEP Rocky Mountain LLC
Federal RGU 31-30-198
Location ID: 316487**



Location from West side



Location from Southeast corner