

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404022553

Date Received:
12/10/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
ERIN JOSEPH	970-515-1169	ECMCInspections@Oxy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714300142
Inspection Date: 11/14/2024 FIR Submit Date: 11/19/2024 FIR Status:

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID:

Location Name: Number: County:
Qtrqtr: SESW Sec: 29 Twp: 2N Range: 68W Meridian: 6
Latitude: 40.105497 Longitude: -105.022060

FACILITY - API Number: 05-123-00 Facility ID: 488157

Facility Name: Rasmussen Federal 35-29 Flowline Number:
Qtrqtr: SESW Sec: 29 Twp: 2N Range: 68W Meridian: 6
Latitude: 40.105497 Longitude: -105.022060

CORRECTIVE ACTIONS:

1 CA# 200527

Corrective Action: Secure access to excavation in compliance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v Date: 12/03/2024

Response: CA COMPLETED Date of Completion: 11/25/2024

Operator Comment: The snow fencing was fixed around the Rasmussen Federal 35-29 Flowline and Rasmussen 36-29 Flowline excavations on 11/25/24.

ECMC Decision:

ECMC
Representative:

2 CA# 200528

Corrective Action: If soil is to be stockpiled on location Operator shall install a sign to denote if the stockpile is clean or contaminated. If soil stockpile is contaminated Operator will collect a soil sample from underneath the observed soil stockpile area prior to spill closure. Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 12/03/2024

Response: CA COMPLETED

Date of Completion: 11/25/2024

Operator Comment: Soil stockpiles were removed from the Rasmussen 36-29 Flowline excavation area on 11/25/24. Soil samples were collected from underneath the observed soil stockpile area on 12/2/24. There were no soil stockpiles associated with the Rasmussen 35-29 flowline excavations as soil was removed from those locations via hydrovac.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH

Signed: _____

Title: SR REGULATORY ADVISOR

Date: 12/10/2024 2:11:41 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404022553	FIR RESOLUTION SUBMITTED
404022558	LOCATION PHOTO

Total Attach: 2 Files