

Inspection Photos

12/10/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335053

Inspection Doc: 718100094

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335053



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335053



Photo 2: See comments under photo 1. Photos also show areas on the west end of the Location that or not necessary for production have not been reclaimed pursuant to 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335053



Photo 3: Photos taken from the central areas of the current pad, facing southwest and northwest. Photos show areas on the west end of the Location that or not necessary for production have not been reclaimed pursuant to 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335053



Photo 4: Photos taken from the west end of the Location, facing northeast and south east. Photos shows areas on the west end of the Location that or not necessary for production have not been reclaimed pursuant to 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335053



Photo 5: Photo taken from the secondary containment measure at the battery. Photo shows Operator has loosely placed bolts within the holes observed in the metal walls; BMP remains inadequate to contain a spill or release.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335053



Photo 2: Photo taken from the secondary containment measure at the battery. Photo shows Operator appears to have placed electrical tape within compromised areas of at the containment BMP; tape is peeling from the metal; BMP remains inadequate to contain a spill or release.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335053



December 10, 2024

Photo 7: Photo taken from the secondary containment measure at the battery. Photo shows Operator has placed loose bolts within holes, and what appears electrical tape within compromised areas of at the containment BMP; BMP remains inadequate to contain a spill or release.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources