

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2024

Submitted Date:

12/12/2024

Document Number:

715500995

FIELD INSPECTION FORM

Loc ID 315451 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 74290
Name of Operator: RETAMCO OPERATING INC
Address: PO BOX 790
City: RED LODGE State: MT Zip: 59068

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Glennon, Joe	(406) 446-1568	joeglennon@retamco.com	
Hunt, Christina	(303) 674-7324	Hunt4energy@earthlink.net	
Gose, Tom	(210) 216-0819	tomgose@retamco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
101748	PIT	AC	09/23/1999		-	PHILADELPHIA CREEK 40	AC
230845	WELL	PR	03/01/2024	GW	103-08514	PHILADELPHIA CREEK 40	PR

General Comment:

[ECMC Inspection Report Summary](#)

On Wednesday, 12/11/2024, Inspector Kirby Burchett, conducted a routine field inspection at Retamco Operating Inc. on the Philadelphia Creek 40 well, Location #315451, in Rio Blanco County, Colorado.

This location is within or close proximity to a Parks & Wildlife (CPW) District and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issue was observed:

1. Caps missing on separator relief vent risers.
2. One pit ID. 2 pits on location.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	406-446-1568	Date:	
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:	Separator Fencing wire with mesh top		
Corrective Action:		Date:	
Type	PIT		
Comment:	Meter run Fencing wire with mesh top		
Corrective Action:		Date:	

Equipment:

Type:		#		corrective date
Other		1		
Comment:	Wellhead tree			
Corrective Action:			Date:	
Gas Meter Run		1		
Comment:				
Corrective Action:			Date:	
Deadman # & Marked		3		
Comment:				
Corrective Action:			Date:	
Bradenhead		1		
Comment:				

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Missing caps on vent risers		
Corrective Action:	Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.		Date: 12/28/2024
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 101748 Type: PIT API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 230845 Type: WELL API Number: 103-08514 Status: PR Insp. Status: PR

Producing Well

Comment: [October 2024 Production Report](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms						
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 101748 Lat: 39.931669 Long: -108.734470

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action Date: _____

Fencing:

Fencing Type: Netting/Fence com Fencing Condition: Adequate

Comment:

Corrective Action Date: _____

Netting:

Netting Type: Metal Grid Netting Condition: Good

Comment:

Corrective Action Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: 2 pits on location with 1 Pit ID

Corrective Action Submit paperwork required so that both pits are documented in ECMC database. Date: 01/12/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500996	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6823247