

Inspection Photos

Loc: 484358

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 12/12/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



Inspection Photos



Photo 2. Facing back west toward the flowline disturbance. The vegetation is not establishing along the flowline. It appears this area was reseeded however, soils need to be stabilized with BMP's such as mulch ect.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 12/12/2024

Inspection Photos



Photo 3. There is dark stained soils at the wellsite and engine compressor. Impacted soils need immediate clean up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 12/12/2024

Inspection Photos



Photo 4. Facing northwest at the wellsite. Stained oily soils sprayed out on both side of the compressor.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 12/12/2024

Inspection Photos




Photo 5. North side of the compressor facing west. Stained oily soils sprayed out on both side of the compressor. Vehicles are driving thru and tracking this area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 12/12/2024

Inspection Photos



Photo 6. There is oil fluid inside the engine skid that must be cleaned up. The grey drum needs to be placed into secondary containment and labeled.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 12/12/2024

Inspection Photos



Photo 7. North side of the location facing southeast. The vegetation is not establishing in this area and will need to be reseeded before the upcoming growing season.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 12/12/2024

Inspection Photos



Photo 8. North side of the location facing east/ The wattles have been displaced and need to be reinstalled.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 12/12/2024