

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**

Section/Township/Range: 31 6S93W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 3393 Lack of stabilization/compaction



Photo # 3394 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 3395 Lack of stabilization/compaction



Photo # 3396 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad
Location ID: 334711



Photo # 3397 Lack of stabilization/compaction



Photo # 3398 Lack of stabilization/compaction