

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 44-7 Pad

Location ID: 439173



Photo # 3227 From entrance to location



Photo # 3228 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 44-7 Pad

Location ID: 439173



Photo # 3229 Location



Photo # 3230 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 44-7 Pad

Location ID: 439173




Photo # 3231 Location



Photo # 3232 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 44-7 Pad

Location ID: 439173



Photo # 3233 Location



Photo # 3234 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 44-7 Pad

Location ID: 439173



Photo # 3235 Location



Photo # 3236 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 44-7 Pad

Location ID: 439173



Photo # 3237 Location



**Photo # 3238 Hole in separator unit/wildlife hazard
/available for entry by wildlife**



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 44-7 Pad

Location ID: 439173



Photo # 3239 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3240 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 44-7 Pad

Location ID: 439173



**Photo # 3241 Summit Midstream meter house not listed in
FORM 2A/not in compliance with CECMC rules**