

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2024

Submitted Date:

12/09/2024

Document Number:

713400527

**FIELD INSPECTION FORM**Loc ID 323790 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456910	Domestic Tap	AC	08/28/2018		-	Domestic Tap 34NENW	AC

**General Comment:****CECMC Inspection Report Summary**

On 12/5/2024 at approximately 14:40 hours, Compliance Inspector Dusty Popejoy conducted a follow up domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap34NENW at Location ID #323790 Facility #456910 in Garfield County, Colorado.

Please refer to inspection 708903759 conducted on 05/9/2024, previous corrective action has not been completed & CA date remains 12/26/2023

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Equipment - PRV vent line does not comply with CECMC pressure safety device rules with a CA date of 12/26/2023

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

**Location****Lease Road:**

Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Other	# 1		
Comment:	Domestic tap		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	PRV vent line does not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC pressure safety device rules	Date:	12/26/2023

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	456910	Type:	Domestic Tap	API Number:	-	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:	While there, I observed the domestic tap is derived from TEP's sales line. The pressure is regulated by a big Joe regulator. Following regulator there's a fluid knock out equipped with a PRV, following the knock out there's a little Joe regulator & after the regulator there's an in line odorizer. Fittings appear to be adequate.								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
ECMC Comments									
Comment							User	Date	
Please refer to Equipment for corrective action.							popejoyd	12/09/2024	
Domestic tap inspection only									
Attached Documents									
You can go to ECMC Images ( <a href="https://ecmc.state.co.us/weblink/">https://ecmc.state.co.us/weblink/</a> ) and search by document number:									
Document Num	Description	URL							
404021244	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817678">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817678</a>							
713400528	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817676">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817676</a>							