

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404031190

Date Received:
12/16/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17330 PRESTON RD STE 200D-208

City: DALLAS State: TX Zip: 75252

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Brandon Parks

bparks33@gmail.com

Sanchez, Chris

chris.sanchez@state.co.us

Bulf, Cathy

cathybulf@gmail.com

Butler, Brad

972-345-9195

butleroil@yahoo.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601700

Inspection Date: 12/12/2024

FIR Submit Date: 12/13/2024

FIR Status: _____

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC

Company Number: 10797

Address: 17330 PRESTON RD STE 200D-208

City: DALLAS State: TX Zip: 75252

LOCATION - Location ID: 484358

Location Name: Red Rocks Number: 1-16 County: LAS ANIMAS

Qtrqtr: NENE Sec: 1 Twp: 30S Range: 55W Meridian: 6

Latitude: 37.464488 Longitude: -103.518825

FACILITY - API Number: 05-071-00 Facility ID: 484677

Facility Name: Red Rocks Number: 1-16

Qtrqtr: NENE Sec: 1 Twp: 30S Range: 55W Meridian: 6

Latitude: 37.464488 Longitude: -103.518825

CORRECTIVE ACTIONS:

1 CA# 201054

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.
Implement or modify BMPs for improved material handling and spill prevention.
Immediately clean up area. 24-48 hours to implement improved procedures. 1002.f.
(2)B.
Notify area EPS and report to other agencies as appropriate.

Date: 12/13/2024

Response: CA COMPLETED

Date of Completion: 12/16/2024

Operator Comment: Rule 912.a. - Oil stained soil from the compressor engine have been removed and will be disposed at the Trinidad Landfill. Photos attached. Rule 1002.f(s)B. - DEO has implemented additional training for new and established personnel for spill/release prevention and control. Attempted EPS notified by phone, notification provided per this FIRR.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 201056

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/16/2024

Response: CA COMPLETED

Date of Completion: 12/16/2024

Operator Comment: rule 1002.f(2)C - Perimeter sormwater controls reestablished - wattles installed. Photos attached.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Rule 912.a - Stained soil from the compressor motor oil has been removed, photos attached. Rule 1002.f.(2)B - Additional training for all DEO personnel in spill/release management has been implemented. Attempted contacting area EPS by phone, EPS notified per this FIRR. DEO has implemented the approved interim reclamation plan for this location and has noted minimal progression. Investigation is ongoing to develop a decompaction, reclamation, stabilization, and seed application plan that will provide the highest likelihood of success in this arid area of Colorado.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathy Bulf

Signed: _____

Title: Manager

Date: 12/16/2024 7:58:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|-------------------------------|
| 404031192 | Soil Clean Up |
| 404031193 | Stormwater Control Maintained |

Total Attach: 2 Files