

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET

DENVER, COLORADO 80203
(303) 894-2109 FAX
(303) 894-2100



DENNIS R. BICKNELL
Director

PATRICIA C. BEAVER
Technical Secretary

ROY ROMER
Governor

November 13, 1992

Mr. Harold Frauli
Midwestern Exploration Co.
P.O. 1884
Liberal, Kansas 67905-1884

RE: Mayberry #2, Greenwood Field
SWNW Section 10-T34S-R41W
Baca County, Colorado

Dear Sir:

On November 4, 1992 the Mayberry #2 disposal well failed a COGCC mechanical integrity pressure test since the tubing-casing annulus would not pressure up to allow for testing. Per COGCC rule 319 b. (5) the well must be repaired and satisfactorily pass a mechanical integrity pressure test or be plugged and abandoned no later than May 12, 1993. The well is required to be shut-in and physically disconnected from the flowline until repaired and passes a pressure test. Notification must be given to the Commission prior to conducting the pressure test so that we may have the opportunity to witness it. Additionally, notify the Commission by Sundry Notice (OGCC Form 4) of the problems found and the action taken to rectify the situation.

If you have any questions feel free to contact me.

Very truly yours,

Larry Robbins
Petroleum Engineer

cc: Files
Mayberry #2.MIT