

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404031198

Date Received:

12/17/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17330 PRESTON RD STE 200D-208

City: DALLAS State: TX Zip: 75252

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Sanchez, Chris</u>		<u>chris.sanchez@state.co.us</u>
<u>Bulf, Cathy</u>		<u>cathybulf@gmail.com</u>
<u>Butler, Brad</u>	<u>972-345-9195</u>	<u>butleroil@yahoo.com</u>
<u>Brandon Parks</u>		<u>bparks33@gmail.com</u>
<u>Brandon Parks</u>		<u>bparks33@gmail.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601702

Inspection Date: 12/12/2024

FIR Submit Date: 12/13/2024

FIR Status: _____

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC

Company Number: 10797

Address: 17330 PRESTON RD STE 200D-208

City: DALLAS State: TX Zip: 75252

LOCATION - Location ID: 481115

Location Name: Red Rocks Number: 1-13 County: _____

Qtrqtr: NWN Sec: 1 Twp: 30S Range: 55W Meridian: 6
W

Latitude: 37.465260 Longitude: -103.533560

FACILITY - API Number: 05-071- -00 Facility ID: 481115

Facility Name: Red Rocks Number: 1-13

Qtrqtr: NWN Sec: 1 Twp: 30S Range: 55W Meridian: 6
W

Latitude: 37.465260 Longitude: -103.533560

CORRECTIVE ACTIONS:

1 CA# 201061

Corrective Action:

Date: 12/16/2024

Implement or modify BMPs for improved material handling and spill prevention. Immediately clean up area. 24-48 hours to implement improved procedures. 1002.f.(2)B. Immediately comply with material handling and guidance per MSDS or product data sheet. Notify area EPS and report to other agencies as appropriate.

Response: CA COMPLETED

Date of Completion: 12/17/2024

Operator Comment: White material at the surface of the wellhead has been removed and will be properly disposed at the Trinidad Landfill. DEO personnel continues to investigate and identify the white substance near the wellhead noted in the inspector's photos and will report as required. Rule 1002.f.(2)B - DEO field personnel are engaging in training of material handling, spill prevention, response, response equipment and communication protocol. DEO notified area EPS by phone, additional notification provided through this FIRR.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 201062

Corrective Action: Operator shall abide by the reclamation rules to minimize surface disturbances per the 1002e rule.

Date: 12/13/2024

Response: CA COMPLETED

Date of Completion: 12/13/2024

Operator Comment: Rule 1002.e - All DEO, contract and third party personnel associated with the well with whom DEO has contact have been instructed not to travel outside the boundary of the original access road. DEO will continue to direct all parties associated with the well to travel only on the boundary of the original access road.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 201063

Corrective Action: Comply with 1003 Rules.

Date: _____

Response: CA COMPLETED

Date of Completion: 12/16/2024

Operator Comment: DEO has implemented the approved interim reclamation plan for this location and has noted minimal progression. Investigation is ongoing to develop a decompaction, reclamation, stabilization, and seed application plan that will provide the highest likelihood of success in this arid area of Colorado.

ECMC Decision: _____

ECMC Representative: _____

4 CA# 201064

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/16/2024

Response: CA COMPLETED

Date of Completion: 12/16/2024

Operator Comment: Rule 1002.f.(2) C - Perimeter stormwater controls have been put in place and maintained where needed.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

DEO personnel continues to identify and will report the white substance near the wellhead noted in the inspector's photos. This may have occurred during recent workover activity. The wellhead sign and wildlife fencing has been replaced, photo attached. Wattles have been put back in place for stormwater control.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathy Bulf

Signed: _____

Title: Manager

Date: 12/17/2024 3:08:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404031200	Photo of Wellhead area and Sign
404032209	Photo of Stormwater Control Reestablished

Total Attach: 2 Files