

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2024

Submitted Date:

12/11/2024

Document Number:

715500991

FIELD INSPECTION FORMLoc ID 315047 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 74290

Name of Operator: RETAMCO OPERATING INC

Address: PO BOX 790

City: RED LODGE State: MT Zip: 59068

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gose, Tom	(210) 216-0819	tomgose@retamco.com	
Glennon, Joe	(406) 446-1568	joeglennon@retamco.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Hunt, Christina	(303) 674-7324	Hunt4energy@earthlink.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230164	WELL	PR	06/01/2021	GW	103-07823	PHILADELPHIA CREEK 7	PR

General Comment:**ECMC Inspection Report Summary**

On Wednesday, 12/11/2024, Inspector Kirby Burchett, conducted a routine field inspection at Retamco Operating Inc. on the Philadelphia Creek 7 well, Location #315047, in Rio Blanco County, Colorado.

This location is within or close proximity to a Parks & Wildlife (CPW) District and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issue was observed:

1. Caps missing on separator relief vent risers.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Operators will ensure that signs are well maintained and legible, and will replace damaged or vandalized signs within 30 days of discovery that the sign is no longer legible or is damaged.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 406-446-1568

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Type: Other	# 1		
Comment:	Wellhead tree		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	Vent riser caps missing		
Corrective Action:	Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.		Date: 12/27/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:	Unlined				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	230164	Type:	WELL	API Number:	103-07823	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	October 2024 Production Report								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Drains				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404025018	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821380
715500992	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821373