

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2024

Submitted Date:

12/11/2024

Document Number:

715800398

FIELD INSPECTION FORM

Loc ID 318276 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241019	WELL	SI	08/01/2024	OW	123-08807	CHARLES C BELL 2	SI

General Comment:[This is a Wellsite Audit/Inspection.](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Faded hard to read and needs to be replaced		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	01/11/2025

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	electric panel, meter box and transformers		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	241019	Type:	WELL	API Number:	123-08807	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment: SI									
Corrective Action:									
Date:									
BradenHead									
Date of Last Brhd Test: 04/15/2024									
Annual Brhd Completed? Yes									
Last Brhd Test Results									
Initial Surf Csg Pressure: 0									
Fluid Type:									
End Surf Csg Pressure: 0									
Comment: Plumbed to surface.									
Corrective Action:									
Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input type="text"/>						Date: <input type="text"/>
Corrective Action: <input type="text"/>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Wednesday 12-11-2024 at approximately 1500 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection:</p> <p>Operator:KP Kauffman</p> <p>Location # 318276</p> <p>API #05-123-08807</p> <p>Well name: Charles C Bell 2</p> <p>County: Weld</p> <p>Weather:Cloudy, Clear</p> <p>Temp: 53*</p> <p>Location:Dry</p> <p>While there, I observed a wellsite, SI at the time of inspection.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>605.g Signs and Markers General Condition: CA date 1-11-2025</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	12/11/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404025011	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821378
715800400	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821377