

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY C Pad

Location #: 311695



Photo # 3669 From entrance to location




Photo # 3670 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY C Pad

Location #: 311695



Photo # 3671 Location



Photo # 3672 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY C Pad

Location #: 311695



Photo # 3673 Location



Photo # 3674 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY C Pad

Location #: 311695



Photo # 3675 Location



Photo # 3676 PRV vent line on tank burner does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY C Pad

Location #: 311695



Photo # 3677 PRV vent line on tank burner does not comply with CECMC pressure safety device rules



Photo # 3678 Tank label lacks capacity