

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404034335

Date Received:

12/18/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LLC

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>General</u>		<u>CO2Source_Regulatory@kindermorgan.com</u>
<u>Longworth, Mike</u>		<u>mike.longworth@state.co.us</u>
<u>Wheeler, Steven</u>		<u>steven.wheeler@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001501

Inspection Date: 10/25/2024

FIR Submit Date: 12/06/2024

FIR Status:

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LLC

Company Number: 46685

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 313601

Location Name: YE (YELLOW JACKET)-N37N18W Number: 2NWNW County:

Qtrqtr: NWN W Sec: 2 Twp: 37N Range: 18W Meridian: N

Latitude: 37.497860 Longitude: -108.809195

FACILITY - API Number: 05-083-00 Facility ID: 313601

Facility Name: YE (YELLOW JACKET)-N37N18W Number: 2NWNW

Qtrqtr: NWN W Sec: 2 Twp: 37N Range: 18W Meridian: N

Latitude: 37.497860 Longitude: -108.809195

CORRECTIVE ACTIONS:

1 CA# 201074

Corrective Action: Submit, attached to a Form 4 Sundry Notice, additional documentation showing risers on the east end of the Location are necessary; including justifications, code citations, etc... for the number of "Annulus Vents" required along the flowline system.

Date: 12/18/2024

Response: CA COMPLETED

Date of Completion: 12/18/2024

Operator Comment: Kinder Morgan participated in a teleconference with ECMC Integrity Engineer Steven Wheeler on 12/17/2024 regarding Field Inspection Report doc. #714001501. Kinder Morgan has completed the corrective actions through a submittal of a Form 4 Sundry Doc.#404034466.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 201075

Corrective Action: Comply with Rule 1004.a- remove flowline risers and any remaining surface equipment on the Location.

Date: _____

Response: CA COMPLETED

Date of Completion: 12/18/2024

Operator Comment: Kinder Morgan participated in a teleconference with ECMC Integrity Engineer Steven Wheeler on 12/17/2024 regarding Field Inspection Report doc. #714001501. Kinder Morgan has completed the corrective actions through a submittal of a Form 4 Sundry Doc.#404034466.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Attached is the submitted Form 4 Sundry Doc. #404034466 for reference.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Curtis Pattillo

Signed: _____

Title: EHS Specialist

Date: 12/18/2024 3:57:26 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404034536	Form 4 Submittal #404034466
404034541	Form 4 Submittal Attachment Binder

Total Attach: 2 Files