

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2024

Submitted Date:

12/12/2024

Document Number:

715500995

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
315451 \_\_\_\_\_ Burchett, Kirby \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 74290  
Name of Operator: RETAMCO OPERATING INC  
Address: PO BOX 790  
City: RED LODGE State: MT Zip: 59068

**Findings:**

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Glennon, Joe	(406) 446-1568	joeglennon@retamco.com	
Hunt, Christina	(303) 674-7324	Hunt4energy@earthlink.net	
Gose, Tom	(210) 216-0819	tomgose@retamco.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
101748	PIT	AC	09/23/1999		-	PHILADELPHIA CREEK 40	AC
230845	WELL	PR	03/01/2024	GW	103-08514	PHILADELPHIA CREEK 40	PR

**General Comment:**

[ECMC Inspection Report Summary](#)

On Wednesday, 12/11/2024, Inspector Kirby Burchett, conducted a routine field inspection at Retamco Operating Inc. on the Philadelphia Creek 40 well, Location #315451, in Rio Blanco County, Colorado.

This location is within or close proximity to a Parks & Wildlife (CPW) District and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issue was observed:

1. Caps missing on separator relief vent risers.
2. One pit ID. 2 pits on location.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**

Overall Good:

**Signs/Marker:**

Type OTHER

Comment: [As Location Entrance signs are replaced: The Well name; The Commission's Location identification number \(ID #\); The Operator's telephone number where it may be reached at all times; and the Telephone number\(s\) for local emergency services \(911 where available\) will be required.](#)

Corrective Action:

Date:

Type WELLHEAD

Comment:

Corrective Action:

Date:

**Emergency Contact Number:**

Comment: [406-446-1568](#)

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

Type PIT

Comment: [Separator Fencing wire with mesh top](#)

Corrective Action:

Date:

Type PIT

Comment: [Meter run Fencing wire with mesh top](#)

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Other

# 1

Comment: [Wellhead tree](#)

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

# 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Missing caps on vent risers		
Corrective Action:	Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.		Date: <u>12/28/2024</u>

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 101748 Type: PIT API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 230845 Type: WELL API Number: 103-08514 Status: PR Insp. Status: PR

**Producing Well**

Comment: [October 2024 Production Report](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Ditches				
Berms						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:  Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 101748 Lat: 39.931669 Long: -108.734470

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Netting/Fence com Fencing Condition: Adequate

Comment:

Corrective Action  Date: \_\_\_\_\_

**Netting:**

Netting Type: Metal Grid Netting Condition: Good

Comment:

Corrective Action  Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: 2 pits on location with 1 Pit ID

Corrective Action Submit paperwork required so that both pits are documented in ECMC database. Date: 01/12/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404027184	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6823248">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6823248</a>
715500996	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6823247">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6823247</a>