


FORM 6 Rev 11/20	State of Colorado Energy & Carbon Management Commission				<table><tr><td>DE</td><td>ET</td><td>OE</td><td>ES</td></tr></table>				DE	ET	OE	ES																													
	DE	ET	OE	ES																																					
1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109				Document Number: 404005683 Date Received:																																					
WELL ABANDONMENT REPORT																																									
<p>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</p>																																									
ECMC Operator Number: 46290					Contact Name: Lily Clark																																				
Name of Operator: KP KAUFFMAN COMPANY INC					Phone: (303) 8254822																																				
Address: 1700 LINCOLN ST STE 4550					Fax:																																				
City: DENVER State: CO Zip: 80203					Email: lclark@kpk.com																																				
For "Intent" 24 hour notice required,					Name: Revas, Robbie		Tel: (720) 661-7242																																		
ECMC contact:					Email: robbie.revas@state.co.us																																				
Type of Well Abandonment Report: <input checked="" type="checkbox"/> Notice of Intent to Abandon <input type="checkbox"/> Subsequent Report of Abandonment																																									
API Number 05-123-08659-00																																									
Well Name: DITLEV-SIMONSEN B Well Number: 1																																									
Location: QtrQtr: SWSW Section: 31 Township: 2N Range: 67W Meridian: 6																																									
County: WELD Federal, Indian or State Lease Number:																																									
Field Name: SPINDLE Field Number: 77900																																									
Only Complete the Following Background Information for Intent to Abandon																																									
Latitude: 40.089960 Longitude: -104.939400																																									
GPS Data: GPS Quality Value: 1.9 Type of GPS Quality Value: Date of Measurement: 06/21/2007																																									
Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems																																									
<input checked="" type="checkbox"/> Other Developer Agreement																																									
Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Estimated Depth:																																									
Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, explain details below																																									
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, explain details below																																									
Details:																																									
Current and Previously Abandoned Zones																																									
<table><tr><th>Formation</th><th>Perf. Top</th><th>Perf. Btm</th><th>Abandoned Date</th><th>Method of Isolation</th><th>Plug Depth</th></tr><tr><td>SHANNON</td><td>5096</td><td>5117</td><td></td><td></td><td></td></tr><tr><td>SUSSEX</td><td>4646</td><td>4682</td><td></td><td></td><td></td></tr></table>									Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth	SHANNON	5096	5117				SUSSEX	4646	4682																		
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																																				
SHANNON	5096	5117																																							
SUSSEX	4646	4682																																							
Total: 2 zone(s)																																									
Casing History																																									
<table><tr><th>Casing Type</th><th>Size of Hole</th><th>Size of Casing</th><th>Grade</th><th>Wt/Ft</th><th>Csg/Liner Top</th><th>Setting Depth</th><th>Sacks Cmt</th><th>Cmt Btm</th><th>Cmt Top</th><th>Status</th></tr><tr><td>SURF</td><td>12+1/4</td><td>8+5/8</td><td>J-55</td><td>24</td><td>0</td><td>592</td><td>350</td><td>592</td><td>0</td><td>VISU</td></tr><tr><td>1ST</td><td>7+7/8</td><td>4+1/2</td><td>J-55</td><td>11.6</td><td>0</td><td>5230</td><td>300</td><td>5230</td><td>3715</td><td>CALC</td></tr></table>									Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status	SURF	12+1/4	8+5/8	J-55	24	0	592	350	592	0	VISU	1ST	7+7/8	4+1/2	J-55	11.6	0	5230	300	5230	3715	CALC
Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status																															
SURF	12+1/4	8+5/8	J-55	24	0	592	350	592	0	VISU																															
1ST	7+7/8	4+1/2	J-55	11.6	0	5230	300	5230	3715	CALC																															

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 5046 with 2 sacks cmt on top. CIBP #2: Depth 4596 with 2 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 8 sks cmt from 3765 ft. to 3665 ft. Plug Type: CASING Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 642 ft. with 188 sacks. Leave at least 100 ft. in casing 592 CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____
Surface Plug Setting Date: _____ Cut and Cap Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Lily Clark

Title: Director of Engineering Date: _____ Email: lclark@kpk.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

Expiration Date: _____

COA Type	Description
----------	-------------

0 COA	
-------	--

ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
404005702	WELLBORE DIAGRAM
404005703	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)