

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5571 From entrance to location




Photo # 5572 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5573 Location



Photo # 5574 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5575 Location



Photo # 5576 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5577 Location



Photo # 5578 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5579 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 5580 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5581 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 5582 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5583 Unlabeled chemical drum/contents & hazards unknown



Photo # 5584 Unlabeled chemical drum/contents & hazards unknown

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_DOE Compressor Station

Facility ID: 465892



Photo # 5585 Tank battery lacks signage