

Inspection Photos

Location: QB ENERGY HYRUP/2-34B (PAD – 2 0)

Location ID: 334103

Date: 12/30/2024



Dec 30, 2024 at 3:10:42 PM
+39.372726,-108.073429 ±3.89m
Parachute

Photo # 1640 Entrance to location



Dec 30, 2024 at 3:42:03 PM
+39.373020,-108.072422 ±3.84m
Parachute

Photo # 1692 Location

Inspection Photos

Location: QB ENERGY HYRUP/2-34B (PAD – 2 0)

Location ID: 334103

Date: 12/30/2024



Photo # 1641 Location



Photo # 1642 Location

Inspection Photos

Location: QB ENERGY HYRUP/2-34B (PAD – 2 0)

Location ID: 334103

Date: 12/30/2024



Photo # 1662 Location



Photo # 1690 Location

Inspection Photos

Location: QB ENERGY HYRUP/2-34B (PAD – 2 0)

Location ID: 334103

Date: 12/30/2024



Photo # 1701 NE corner of location



Photo # 1702 SE corner of location

Inspection Photos

Location: QB ENERGY HYRUP/2-34B (PAD – 2 0)

Location ID: 334103

Date: 12/30/2024



Photo # 1703 SW corner of location



Photo # 1704 NW corner of location

Inspection Photos

Location: QB ENERGY HYRUP/2-34B (PAD – 2 0)

Location ID: 334103

Date: 12/30/2024



Photo # 1651 Improperly stored chemicals



Photo # 1681 Wildlife hazard



Inspection Photos

Location: QB ENERGY HYRUP/2-34B (PAD – 2 0)

Location ID: 334103

Date: 12/30/2024



Photo # 1684 Wildlife hazard




Photo # 1688 Wildlife hazard

Inspection Photos

Location: QB ENERGY HYRUP/2-34B (PAD – 2 0)

Location ID: 334103

Date: 12/30/2024



Photo # 1693 Inaccurate information



Photo # 1697 Inaccurate information

