

Inspection Photos

January 2nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 306880

Inspection Document #: 714001663

La Plata County, CO

Township: SESW 8 34N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Morrison Federal 2
Location ID: 306880



Photo 1. View of the well pad taken from the access point facing center.



MORRISON FEDERAL 2
SIMCOE LLC
ELEVATION: 6922 API #: 067-08949 DWR #: 70534-F
NAME OF TRIBE: N/A LEASE TYPE: M/A
LEASE #: N/A CA#: N/A
SURFACE LOCATION: SE3/4 SEC 8 - T34N - R6W 1/4 FSL 2424' FWL
BOTTOM HOLE LOCATION: SAME AS SURFACE LOCATION
LATITUDE: 37.22464496 LONGITUDE: -107.5516817
NEAREST ADDRESS: 5830 CR 525
CONTROL CENTER 24 HR. PHONE #: 970-247-6916
EMERGENCY CONTACT #: 911

API #: 067-08949



Photo 2. View of observed spill on location.





Photo 3. Produced water sign is deteriorating and no longer legible/displaying capacity.

Inspection Photos
Location Name: Morrison Federal 2
Location ID: 306880



Photo 4. Signs/placards at separators have deteriorated and are no longer legible.

Inspection Photos
Location Name: Morrison Federal 2
Location ID: 306880



Photo 5. Weedy debris observed dominating cut slope area and interfering with the establishment of desirable vegetation.

Inspection Photos
Location Name: Morrison Federal 2
Location ID: 306880



Photo 6. View of surface owner equipment/piping that remains stored on location.



Photo 7. Erosion issues persist in the cut slope areas.