

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC Johnson 05-05 Pad**  
**Location ID: 334423**




**Location Overview: Location is within High  
Priority/Density/Black Bear Habitat areas & in close proximity  
to NSO Habitat area. Location is approximately 171 yards  
from West Mamm Creek.**

**Section/Township/Range: 5 8S93W**


**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC Johnson 05-05 Pad**  
**Location ID: 334423**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC Johnson 05-05 Pad**  
**Location ID: 334423**



**Photo # 7485 Failure to maintain chemical BMP - Chemical tank containment approximately 2/3 to 3/4 full of fluid/BMP insufficient to contain possible spill**