

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/07/2025

Submitted Date:

01/09/2025

Document Number:

711901672**FIELD INSPECTION FORM**Loc ID 313655 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	steve@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224745	WELL	SI	08/01/2022	OW	087-05130	PETERSON, MAX 1	SI

General Comment:WO - RIG ON LOCATION - P&A IN PROCESS DAY (2) ECMC P&A ORDER # 403980131

Inspected Facilities

Facility ID: 224745

Type: WELL

API Number: 087-05130

Status: SI

Insp. Status: SI

Cement

Cement Contractor

Contractor Name: BOHLER WELL

Contractor Phone:

Surface Casing

Cement Volume (sx):

Circulate to Surface:

Cement Fall Back:

Top Job, 1" Volume:

Intermediate Casing

Cement Volume (sxs):

Good Return During Job:

Production Casing

Cement Volume (sx):

Good Return During Job:

Plugging Operations

Depth Plugs(feet range):

Cement Volume (sx):

Good Return During Job:

Cement Type:

Comment:

SAFETY MEETING- WARM UP - PULL TUBING - WAITING ON WIRELINE (SCHEULING DELAYS EXTREME COLD) SHUT DOWN FOR NIGHT

Corrective Action:

Date:

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment:

P&A IN PROCESS

Corrective Action:

Date:

Workover

Comment:

RIG ON LOCATION

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
P&A DAY (2)	schureky	01/09/2025

Date Run: 1/9/2025 Doc [#711901672]

Page 2 of 2