

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



When well sign is replaced additional information is required



Oily waste and stained soil

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Damaged tank containment



Damaged tank containment

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Well name incorrect on West end location entrance sign



Lacking Stormwater BMP's

KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154



Well name incorrect on tank battery signage



Peeling tank label

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Lacking Stormwater BMP's



Lacking Stormwater BMP's

KT Resources LLC
 Ant Hill Unit 30-42
 Location ID: 316154



REC 503
 Jan 9, 2025 at 10:59:32 AM

EMPACT ANALYTICAL SYSTEMS INC
 365 SOUTH MAIN BRIGHTON, CO 80601
 303-637-0150 www.empactanalytical.com

Meter S/N
 15113460
 D: 374934A


Station Name Ant Hill Unit 30-42
 Station No. 120275546 Producer 31 OP
 Sec 30 Township 2N Range 96W
 Diff 250" Temp Range 0-150" Tube Size 2.068
 Static 200# Absolute 11.82 psig

	Date	Orifice Plate Size	Meter Test Date	Sample Date
GM	3-6-18	0.625 ✓	3-6-18	3-6-18
KB	2-26-19	0.625	2-26-19	3-18-19

Lacking Stormwater BMP's

Calibration overdue

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Stained soil



Lacking Stormwater BMP's

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Location from Northeast corner



Location from Northwest corner and West entrance

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Location from Southwest corner and West entrance



Location from Southeast corner and East entrance