

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2025

Submitted Date:

01/09/2025

Document Number:

715501131**FIELD INSPECTION FORM**Loc ID 316336 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10775Name of Operator: KT RESOURCES LLCAddress: 3381 WESTBROOK LANECity: HIGHLANDS State: CO Zip: 80129**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments6 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Enforcement, ECMC		dnr_cogccenforcement@state.co.us	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266493	WELL	SI	10/01/2023	GW	103-10276	ANT HILL UNIT COUNTY 25-12	SI

**General Comment:****ECMC Inspection Report Summary**

On Thursday, 01/09/2025, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the Ant Hill County 25-12 well, Location #316336, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #715500500 on 7/31/24 and Insp. #702501744 on 8/15/23. NOAV's issued on 10/2/24, Doc. #403943718, with operator response on 10/29/24. The following Corrective Actions are unresolved and original due dates remain:

1. Weeds.
2. Gas meter calibration overdue.
3. Stormwater BMPs need implementation.
4. Stained soils around separator.
5. Tank berm inadequate.
6. Illegible labels.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Faded, peeling and illegible labels		
Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.	Date:	08/11/2024
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: (800) 288-0560

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.		
Corrective Action:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.	Date:	08/23/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
PW/CO	Treater		
Comment:	Stained soil underneath treater		
Corrective Action:	Remove and properly dispose of impacted soil.	Date:	08/31/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks on containments		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration out of compliance.		
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director. All calibration reports will be created, maintained, and made available as operation records.	Date:	08/26/2023

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate			
Comment:	Unlined earth and metal. Corner of metal berm not sealed.			
Corrective Action:	Repair or install berms or other secondary containment devices.			Date: 09/15/2023

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Unlined earth and metal. Metal berm not sealed. Corrective Action addressed under Tanks and Berms: Crude Oil				
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	266493	Type:	WELL	API Number:	103-10276	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <div>November 2024 Production Report Last Production - September 2023</div>									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Gravel				
		Ditches				
		Culverts				
Ditches						
Gravel						

Comment: [Stormwater BMPs need implementation and maintenance.](#)

Corrective Action: [Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Date: 09/15/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501132	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6870494">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6870494</a>