

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2024

Submitted Date:

01/03/2025

Document Number:

694500754**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All inspections
Fischer, Alex		alex.fischer@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Roberts, James	970-620-6589	j75rober@blm.gov	

General Comment:

On 12/12/24, ECMC staff Kris Neidel inspected spill #488744. Weather was sunny and 30 degrees. During the inspection roustabout crews were re-mobilized to the field, it was reported that they were going to continue clean up on spills in the field. The following was observed; tilled and/or ripped soil and vegetation, hydrocarbon staining was observed in soil, due to tilling and spreading the contamination appears distributed, with no defined spill path. Corrective Actions: Remove all visual oil in soil and vegetation (free oil). The entire disturbed area of the spill shall be delineated for Table 915-1, The failed riser is a part of an Unregistered Off-Location Flowline. The operator shall register the flowline location via form 44 per, Rule 1101.b.

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: The following was observed; tilled and/or ripped soil and vegetation, hydrocarbon staining was observed in soil, due to tilling and spreading the contamination appears distributed, with no defined spill path.

Corrective Action: A Form 27 Remediation workplan shall be submitted that; identifies the impacted area and proposes sample locations. The workplan shall describe how the operator will demonstrate that remaining soils are compliant with Table 915-1. When preparing the Workplan, please include comments and COA's from ECMC in the initial Spill Report, doc 404028213.

Date: 03/03/2025

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: 4800

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404047211	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6862388
694500755	photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6862385