

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404061997

Date Received:

01/17/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001646

Inspection Date: 01/02/2025

FIR Submit Date: 01/03/2025

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306896

Location Name: GOEGLEIN GAS UNIT- N35N7W Number: 22SESW County: _____

Qtrqr: SESW Sec: 22 Twp: 35N Range: 7W Meridian: N

Latitude: 37.283326 Longitude: -107.624882

FACILITY - API Number: 05-067- -00 Facility ID: 306896

Facility Name: GOEGLEIN GAS UNIT- N35N7W Number: 22SESW

Qtrqr: SESW Sec: 22 Twp: 35N Range: 7W Meridian: N

Latitude: 37.283326 Longitude: -107.624882

CORRECTIVE ACTIONS:

1 CA# 201455

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 1002.

Date: 01/10/2025

Response: CA COMPLETED

Date of Completion: 01/16/2025

Operator Comment: Impacted soil removed.

ECMC Decision: _____

ECMC Representative:	
----------------------	--

2	CA# 201456	
Corrective Action:	Erosion controls need to be installed and maintained until bare soils are stabilized with desirable perennial vegetation. Seeding needs to be conducted by 11/1/2020.	Date: 05/15/2025
Response:	CA COMPLETED	Date of Completion: 01/16/2025
Operator Comment:	Seeded cut slope.	
ECMC Decision:		
ECMC Representative:		

3	CA# 201457	
Corrective Action:	Erosion controls need to be installed and maintained until bare soils are stabilized with desirable perennial vegetation.	Date: 01/10/2025
Response:	CA COMPLETED	Date of Completion: 01/16/2025
Operator Comment:	Seeded cut slope.	
ECMC Decision:		
ECMC Representative:		

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	Corrective actions completed. See attachment for photos.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Grace Bryson	Signed: _____
Title: permitting specialist	Date: 1/17/2025 11:52:52 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404062006	Completion photos at Goeglein 2

Total Attach: 1 Files