

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2025

Submitted Date:

01/15/2025

Document Number:

699506802**FIELD INSPECTION FORM**Loc ID 320342 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10395Name of Operator: GOODWIN ENERGY MANAGEMENT LLCAddress: 740 S OGDEN STREETCity: DENVER State: CO Zip: 80209**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		michael.hickey@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203506	WELL	PR	08/11/2010	OW	001-09066	SATTERFIELD 1 (OWP)	PR

**General Comment:**

OWP inspection

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 203506 Type: WELL API Number: 001-09066 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 06/08/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: In need of bradnhead test.

Corrective Action:

Date:

**Workover**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment

User

Date

This is an orphan well inspection.  
 Unable to access location at time of inspection due to snow drift on lease road.  
 Well is in need of MIT and annual bradenhead test.  
 At time of inspection weather conditions were cold, clear, light wind.

medinaj

01/15/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506803	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6881321">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6881321</a>