

**Inspection Photos**  
**Location Name: QB Energy DUNN 4-15B (K4E) Pad**  
**Location #: 334945**



**Photo # 9984 From entrance to location**



**Photo # 9985 From entrance to location**

**Inspection Photos**  
**Location Name: QB Energy DUNN 4-15B (K4E) Pad**  
**Location #: 334945**



**Photo # 9986 Location**



**Photo # 9987 Location**





**Inspection Photos**  
**Location Name: QB Energy DUNN 4-15B (K4E) Pad**  
**Location #: 334945**



**Photo # 9988 Location**



**Photo # 9989 Location**

**Inspection Photos**  
**Location Name: QB Energy DUNN 4-15B (K4E) Pad**  
**Location #: 334945**



**Photo # 9990 Location**



**Photo # 9991 Flowline heating insulation damaged/wildlife hazard/available for entry by wildlife**



## Inspection Photos

Location Name: QB Energy DUNN 4-15B (K4E) Pad

Location #: 334945



**Photo # 9992 Hole in secondary containment liner/liner needs maintenance**



**Photo # 9993 Hole in secondary containment liner/liner needs maintenance**

**Inspection Photos**  
**Location Name: QB Energy DUNN 4-15B (K4E) Pad**  
**Location #: 334945**



**Photo # 9994 Possible tank integrity issue/tank appears to lack integrity**



**Photo # 9994 Possible tank integrity issue/tank appears to lack integrity**