

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404063736

Date Received:

01/20/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Reid, Marta

719-688-1638

marta@westernoperating.com

James, Steven

(303) 893-2438

steve@westernoperating.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713600787

Inspection Date: 02/27/2024

FIR Submit Date: 02/29/2024

FIR Status: _____

Inspected Operator Information:

Company Name: WESTERN OPERATING COMPANY

Company Number: 95620

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

LOCATION - Location ID: 324809

Location Name: BUTLER USA-619S45W Number: 10SWNE County: KIOWA

Qtrqtr: SWNE Sec: 10 Twp: 19S Range: 45W Meridian: 6

Latitude: 38.421440 Longitude: -102.444060

FACILITY - API Number: 05-061- -00 Facility ID: 212814

Facility Name: BUTLER USA Number: 1-X

Qtrqtr: SWNE Sec: 10 Twp: 19S Range: 45W Meridian: 6

Latitude: 38.421440 Longitude: -102.444060

CORRECTIVE ACTIONS:

1 CA# 192536

Corrective Action: Comply with Rule 606.

Date: _____

Response: CA COMPLETED

Date of Completion: 06/01/2024

Operator
Comment:

Inspection 713601502 " The two unused tanks and parts have been removed."

ECMC Decision: _____

Date:

Date of Completion: 05/23/2024

Inspection 713601029 "H2S wind sock has been replaced."

ECMC Decision:

--

Signed: _____

Date: 1/20/2025 4:32:28 PM

404063736	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Page 2 of 2