

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/15/2025

Submitted Date:

01/15/2025

Document Number:

715501174

FIELD INSPECTION FORM

Loc ID 315986 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10775
Name of Operator: KT RESOURCES LLC
Address: 3381 WESTBROOK LANE
City: HIGHLANDS State: CO Zip: 80129

Findings:

- 9 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Enforcement, ECMC		dnr_cogccenforcement@state.co.us	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Engineering, ECMC		dnr_cogccengineering@state.co.us	
Adams, Karen	(303) 886-8733	adams@kt-res.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231858	WELL	SI	09/01/2016	GW	103-09529	FEDERAL 33-4-B	SI

General Comment:

[ECMC Inspection Report Summary](#)

On Wednesday, 01/15/2025, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the Federal 33-4-B well, Location #315986, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density, and Other Consultation Habitat regulations.

Follow up inspection in response to compliance issues observed during Insp. #702502145 on 11/15/23. The following Corrective Actions are unresolved and original due dates remain:

1. Bradenhead inaccessible.
2. Mechanical Integrity Test required.
3. Annual Bradenhead report submitted. No Bradenhead access.

Refer to Inspection Photos for observed compliance issues.

While there during normal operations the following compliance issues were observed:

1. Weeds.
2. Gas calibration overdue.

Refer to Inspection Photos for observed compliance issue.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	(800) 288-0560		Date:
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.		
Corrective Action:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.		Date: <u>01/23/2025</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
			corrective date
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow Bradenhead visual inspection.		Date: <u>11/16/2023</u>
Type: Gas Meter Run	# 1		
Comment:	Outside meter. Calibration card inside box. Gas meter calibration out of compliance.		
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.		Date: <u>02/15/2025</u>
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead.		
Corrective Action:			Date:
Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 231858 Type: WELL API Number: 103-09529 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut In - September 2016
November 2024 Production Report
Well is overdue for Mechanical Integrity Test (MIT). MIT requires 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months. Date: 12/16/2023

BradenHead

Date of Last Brhd Test: 07/11/2023 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: ECMC database indicates Bradenhead Test performed on 7/11/23.
Form 17, Doc. #403463916. 12/16/2023

Corrective Action: Verify Form 17 as Bradenhead is not visible or accessible at time of inspection. Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Operator is responsible for maintaining Best Management Practices \(BMPs\) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404059914	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6877815
715501175	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6877811