

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2025

Submitted Date:

01/27/2025

Document Number:

715501189**FIELD INSPECTION FORM**Loc ID 312916 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10409Name of Operator: PEAKVIEW OPERATING COMPANY LLCAddress: 2427 WEST KETTLE CIRCLECity: LITTLETON State: CO Zip: 80120**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Walters, Steve	(720) 402-3081	swalters@peakviewenergy.com	
Wise, Wayne	(405) 826-7013	wwise@peakviewenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222829	WELL	PR	05/17/1973	OW	081-06189	VOLOSHIN-MORTON 1 (-8)	PR

General Comment:**ECMC Inspection Report Summary**

On Monday, 01/27/2025, Inspector Kirby Burchett, conducted a routine audit at Peakview Operating Company LLC, on the Voloshin-Morton #1 (-8) well, Location #312916, in Moffat County, Colorado.

This location is within or close proximity to a Colorado Parks & Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issue was observed:

1. Oily waste at tank battery.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-881-1130

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	Truck Loadout			
Comment:	<p>Oily waste in snow near truck loadout. Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations for materials handling and spill prevention procedures and practices implemented for material handling and spill prevention of materials used, stored, or disposed of that could result in discharges causing pollution of surface waters.</p>			
Corrective Action:	Remove and properly dispose of oily waste and contaminated soil.			Date: 02/12/2025

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Manufacturer		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	222829	Type:	WELL	API Number:	081-06189	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	November 2024 Production Reported								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		Limited stormwater inspection due to snow. Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.				
Corrective Action:						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501191	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892187