

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2025

Submitted Date:

01/29/2025

Document Number:

709100477**FIELD INSPECTION FORM**Loc ID 316915 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments7 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Collin Metz		collin.metz@state.co.us	
Abdul Elnajdi		abdul.elnajdi@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	
Kyle Waggoner		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233168	WELL	PR	02/15/2006	OW	121-05192	SCOTT 2	EI
316915	LOCATION	AC	04/14/2009		-	SCOTT-64S53W 7NWNE	EI

General Comment:

On January 3, 2025, ECMC Staff Krystal Heibel, Abdul Elnajdi, and Collin Metz conducted an on-site inspection. This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Signs for tanks too small to read at a distance, damaged, or missing.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	02/27/2025
Type	TANK LABELS/PLACARDS		
Comment:	Damaged NFPA label on gas tank. Emergency number illegible on gas tank.		
Corrective Action:	Comply with CDPHE and ECMC rules and replace/update NFPA label and emergency phone number.	Date:	01/30/2025

Emergency Contact Number:

Comment:	Emergency contact phone number illegible from a distance.		
Corrective Action:	Operator shall comply with Rule 605.h.	Date:	01/31/2025

Good Housekeeping:

Type			
Comment:	Unused equipment (multiple buckets, hose, plastic, metal post, unused tank, PVC piping, metal piping) observed on location. / Comply with Rule 606		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil				
Comment:	Hydrocarbon impacted soil observed next to loadout container, among tank battery, on pumping unit, on wellhead, and within metal shed			
Corrective Action:	Operator shall remediate the historic release by delineating horizontal and vertical extent of impacted area using the Table 915-1 Protection of Groundwater Soil Screening Level Concentrations and remediate impacts to Table 915-1 standards. Documentation must include a figure showing spill area with sample locations plus laboratory results. This information shall be submitted within a Form 19 submittal.			Date: 02/03/2025

In Containment: No

Comment: Operator is not in compliance with Rule 909.j.(2). Operator has not submitted annual Produced Water Quality Analysis data via a Form 43. No Produced Water Quality Analysis data has been received for 2024. Operator shall submit annual Produced Water Quality Analysis data to the ECMC via a Form 43.

☐ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
Comment:	Hydrocarbon sheen observed in pit.		
Corrective Action:	Per Rule 909.d., Operator will remove the oil or produced hydrocarbons immediately.		
Date:	01/28/2025		
Type:	#		
Comment:	An access pipe was observed that would allow excess waste to flow outside of secondary containment / berms was observed (see photos 12 - 16). Comply with Rule 902.b and Rule 1002.f.(2)B by implementing or modifying BMPs for improved material handling and spill prevention. Prevent any unauthorized discharge. Remove the pipe to prevent unauthorized discharge. If a discharge permit has been acquired, email information to NE EPS Krystal Heibel (krystal.heibel@state.co.us).		
Corrective Action:			
Date:			
Type:	#		

Comment:	Open valves observed on tanks.			
Corrective Action:	Install or repair wildlife protection equipment and prevent any unauthorized discharge by adding bull plugs.		Date:	02/27/2025
Type:		#		
Comment:	Multiple valves not securely fitted at tanks and wellhead. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Burrows observed in berms.			
Corrective Action:	Repair or install berm or other secondary containment devices per Rule 609.b.			Date: 03/27/2025

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 233168	Type: WELL	API Number: 121-05192	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 316915	Type: LOCATION	API Number: -	Status: AC	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100478	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6894434