

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/29/2025

Submitted Date:

01/31/2025

Document Number:

713400660**FIELD INSPECTION FORM**Loc ID 455725 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Heil, John		john.heil@state.co.us	
, LARAMIE		cogccnotifications@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455730	WELL	DG	01/25/2025	LO	077-10600	Hayward 0993-25-07E	DG

**General Comment:****CECMC Inspection/Audit Report Summary**

On 1/29/2025 at approximately 12:40 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit for a Drilling Operation at LARAMIE ENERGY LLC Hayward/0993-25-09 Pad at Location ID #455725 in Mesa County, Colorado.

While there, I observed drilling crew drilling production casing on Hayward #0993-25-07E well.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Stormwater - Failure to maintain chemical BMP's/Failure to cover materials with a CA date of 02/7/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.



**Location****Lease Road:**

Type	Access		
comment:	Access		
Corrective ActionL		Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	1-800-891-6191/911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 1		corrective date
Comment:	Drilling Rig with all associated equipment		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	



Inspected Facilities									
Facility ID:	455730	Type:	WELL	API Number:	077-10600	Status:	DG	Insp. Status:	DG
Well Drilling									
Rig:	Rig Name: H&P 542		Pusher/Rig Manager:						
	Permit Posted: SATISFACTORY		Access Sign: SATISFACTORY						
Well Control Equipment:									
	Pipe Ram:		Blind Ram:		Hydril Type:				
	Pressure Test BOP:		Test Pressure PSI:		Safety Plan:				
Drill Fluids Management:									
	Lined Pit:		Unlined Pit:		Closed Loop:		Semi-Closed Loop:		
	Multi-Well:		Disposal Location:						
Comment:	01/29/2025 at approximately 12:40 hours checked operators Form 2 and observed drilling operations with Laramie Energy company man.  Refer to document number 404066243								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction
Berms						
Ditches						
		Ditches				
				Material Handling And Spill Prevention	Fail	Failure to maintain chemical BMP's
Sediment Traps						
		Sediment Traps				
				Covering Materials	Fail	Failure to cover materials
		Compaction				Light compaction
		Berms				

Comment: 1. Failure to maintain chemical BMP's, refer to photos  
 2. Failure to cover materials, refer to photos  
 Informed company man about observed compliance issues, he said they would take care of it and get it cleaned up.

Corrective Action: **Comply with CECMC Storm water rules**

Date: 02/07/2025

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Please refer to Stormwater for corrective action.	popejoyd	01/31/2025
Limited storm water inspection/audit due to snow cover.		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400661	Inspection-Audit Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900108">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900108</a>